Release Notes Bulletin

TRIMBLE DINI 0.3/0.7: NEW CCD-LINE FIRMWARE R2.2.1 RELEASE NOTES

Introduction

These release notes contain information about the Trimble DiNi 0.3/0.7: New CCD Line. In a newly purchased instrument, this version of firmware may already be installed. It is also available for download from www.trimble.com:

New Firmware R2.2.1   http://trl.trimble.com/dscgi/ds.py/Get/File-915274/DiNiUpdate_R2_2_1.zip

Upgrading From a Previous Version of Firmware

If you have a Trimble DiNi 0.3/0.7 produced from April 2019, it may running an older version of firmware, you can upgrade to version R2.2.1 by yourself.

Serial number affected:

Trimble DiNi 0.3 with serial number from ≥750500
Trimble DiNi 0.7 with serial number from ≥774004

To upgrade your Trimble DiNi 0.3/0.7 to firmware version

Please refer Service Manual: http://trl.trimble.com/docushare/dsweb/Get/Document-915593/Trimble_DiNi_Maintenance_Manual_ver201.6_2019-06-03.pdf

Trimble recommends that customers regularly check www.trimble.com for the latest versions of software and firmware for all of their Trimble products.

Solved Issues

Since introduction of the Trimble DiNi in 2007, the CCD-Line is now replaced by a backward compatible new CCD-Line. The new CCD-Line requires a new firmware R2.2.1.

For more information

For more information, contact your local Trimble Distribution Partner.

Geospatial.trimble.com

TRANSFORMING THE WAY THE WORLD WORKS

Trimble