



**Main Components**  
 SX10 Scanning Total Station in Kit  
 SX10 Instrument Case  
 Tribrach with bi-directional optical plummet  
 Cleaning cloth  
 USB 2.0 data cable  
 Rain cover

SX10-100-00 1

**Accessories**

- 58012029 2 360 Prism with height adapter
- 58128001 3 YX&S-Series 360 Prism with height adapter
- SLSU-S2010 4 Traverse Kit
- 58026007 5 Traverse prism + sighting target
- 571126273 6 Mini prism with pole
- 57012007 7 Reflective foil targets, 25\*25mm + 60\*60mm
- 99511-30 8 Battery – 6.5Ah
- SLSU-S2016 9 Autolock Power Kit – 2 batteries, no charger
- SLSU-S2016-3 10 Robotic Power Kit – 3 batteries, 3 battery holder + cable, no charger
- 59369-00 11 3 battery external holder
- 73838019 12 Cable – 2.5m, Hirose 6 pin to Hirose 6 pin
- 101070-00-XX\* 13 Dual Battery Charger with power supply and cord
- 101070-02-XX\* 14 2 x Dual Battery Charger with power supplies and cords
- 73836019 15 Cable – 30m, Car battery (croc clips) to Hirose 6 pin
- 90553-TR-SUR 16 Tripod – Dual Clamp Tri+Max
- 510003007 17 Standard Telescopic Rod 2.6m
- 571126286 18 Standard Trimble Blipod
- 52618 19 Tape Measure, Metric/Tenths
- 78606019 20 Laser Tribrach
- 78607007 21 Tribrach without optical plumb
- 78608007 22 Prism base with level and built in optical plummet
- 70600007 23 Tribrach with Bi-Direction optical plummet

\* XX Varies by Region.



Items are not to scale.